

**Green
works**
CIRCULAIR EN DUURZAAM BOUWEN

A close-up photograph of a brick wall. The bricks are reddish-brown with some darker, weathered spots. A sharp vertical shadow runs down the center of the image, separating two sections of the wall. To the right, a portion of a modern building with large glass windows is visible, reflecting a blue sky and bare tree branches.

GREENWORKS MENMERKEN				
PRODUCT: MBI GEOSTYLISITX				
TOEPASSING: buitenwandafwerking voor de gevel				
Duurzame materiaal- en productie eigenschappen				
 HERNUEUWBAAR EN/OF RECYCLING INHOUTSTOFFEN	 HERKOMST GRONDSTOFFEN	 DUURZAME ENERGIEBRON	 RECYCLING PRODUCTIEAFVAL	 HERKOMST PRODUCT
> 95%	≤ 50	volledig	100% intern	< 200 km
> 50%	50-800 km	deels	100% extern	200-800 km
 BILZONDERE MILIEUWINST	 ONDERHOUD TIJDENS GEBRUIK	 REPARABEL	 BIOLOGISCH AFBREEKBAAAR	 HERSRIJKBAAARHEID
ja	onderhoudsvrij	ja	ja	ja
nee	onderhoudsarm	nee	nee	nee

De Greenworks kenmerken zijn gebaseerd op de levenscyclusanalyse (LCA)

Kenmerk van toepassing op dit product Kenmerk niet van toepassing op dit product

Opgemaakt d.d.: 01-09-24